

OOCABOOLINA OUTSTATION

2019 The refurbishment continued during 2019, only one working bee in May. Work undertaken included,

Western entry – this was one of the two major projects for the year. Previously the entry was covered by sheets of GI on a steel frame. The carpentry skills of Mal Kirkham and Ray Hutchinson along with help from Phil Gaukroger and painting of timber surfaces ably carried out by Jan Hutchinson and her team soon saw this transformed.



Walls & Kitchen Fireplace – we continued to thoroughly clean all the internal walls in preparation for painting. With the exception of the kitchen walls each was given a primer/undercoat and first top coat and removed broken bricks from fireplace.



Concrete floors – Loose and fretted concrete in the two bedroom floors was removed, then thoroughly swept and washed and made ready for the pouring of a surface levelling compound.

Internal door jambs – work continued on the repair and replacement of the internal door jambs and made ready for primer and undercoating where required.

Bedroom External Doors – Both exterior door openings cleaned of paint and carefully measured for later installation of French Doors and security screens.