

## OOCABOOLINA OUTSTATION

**2020** The refurbishment continued during 2020, two working bees in June and August. Work undertaken included: -


**Windows & Screens** – 6 white ant ridden wooden window frames removed and replaced with aluminium frames , new security screens replaced original iron bars



**Tank** – tap connected on wall of hut & 27m of earthenware pipe removed and replaced with new 90mm stormwater PVC.



**Bedroom floors** – both were cleaned and a surface levelling compound poured applied



**Athel Pines** – two pines outside eastern fence removed and all but “mother tree” stump removed, burned and ash buried.



**Bedroom Doors** – frames replaced and measured for installing of French Doors and security screens during 2021.

**Painting** – continued painting of internal walls & doors.



**Outdoor Table** - A table made and supplied by Sian was installed near the BBQ pit and painted.



**Ranger Support** - We were again well supported by Rangers Sian and Joeulla providing equipment prior to us arriving each trip and for the many hours spent on telephone and emails